

WAC 296-803-40005 Provide appropriate means to control energy.

You must provide the means necessary to isolate, secure, or block machines and equipment from energy sources.

Note: Examples of means to control energy include:

1. Locks.
2. Tags.
3. Chains.
4. Wedges.
5. Key blocks.
6. Adapter pins.
7. Self-locking fasteners.
8. Blank flanges.
9. Cribbing.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, and 49.17.060. WSR 17-18-075, § 296-803-40005, filed 9/5/17, effective 10/6/17; WSR 09-16-108, § 296-803-40005, filed 8/4/09, effective 11/1/09; WSR 04-15-105, § 296-803-40005, filed 7/20/04, effective 11/1/04.]