

WAC 296-54-52007 Cutting system operation. (1) When possible, keep the chain shot cone clear of the operator and other persons.

(2) Follow the chain manufacturer's recommendation for chain speed. "Boosting" or exceeding the manufacturer's recommendation is prohibited.

(3) Maintain proper chain tension.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, 49.17.060, and chapter 49.17 RCW. WSR 17-17-131, § 296-54-52007, filed 8/22/17, effective 10/22/17.]