

WAC 296-803-500 Summary.**Your responsibility:**

To make sure energy control procedures are used and include these requirements.

You must meet the requirements...	in this section:
Energy Control Procedures	
Use energy control procedures	WAC 296-803-50005
Applying Lockout or Tagout Devices	
Meet these requirements when applying lockout or tagout devices	WAC 296-803-50010
Meet these additional requirements when applying lockout devices	WAC 296-803-50015
Meet these additional requirements when applying tagout devices	WAC 296-803-50020
Stored Energy	
Protect employees from the hazards of stored and residual energy	WAC 296-803-50025
Verifying Machine Isolation	
Verify that the machine or equipment is safe before starting work	WAC 296-803-50030
Removing Energy Control Devices	
Meet these requirements when removing lockout or tagout devices and energizing the machine or equipment	WAC 296-803-50035
Temporary Energization	
Meet these requirements if it is necessary to temporarily energize a machine, equipment, or component for testing or positioning	WAC 296-803-50040
Shift or Personnel Changes	
Protect employees during shift or personnel changes.	WAC 296-803-50045
Group Lockout/Tagout	
Protect employees working in a group	WAC 296-803-50050
Meet these additional requirements if more than one group is used	WAC 296-803-50055
Outside Employers	

You must meet the requirements...	in this section:
Coordinate with outside employers servicing or maintaining your machines or equipment	WAC 296-803-50060

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, and 49.17.060. WSR 17-18-075, § 296-803-500, filed 9/5/17, effective 10/6/17; WSR 04-15-105, § 296-803-500, filed 7/20/04, effective 11/1/04.]