

WAC 296-806-42010 Provide safe access to conveyors. You must provide a way to safely inspect and maintain conveyors located more than seven feet from the floor.

Reference: Some additional requirements for protecting employees inspecting and maintaining conveyors can be found in:
1. Lockout/tagout (control of hazardous energy), chapter 296-803 WAC.
2. Personal fall arrest systems, WAC 296-24-88050.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, 49.17.060. WSR 15-24-102, § 296-806-42010, filed 12/1/15, effective 1/5/16; WSR 04-14-028, § 296-806-42010, filed 6/29/04, effective 1/1/05.]