

**WAC 296-806-45016 Guard automatic turning lathes.** You must install hoods that completely enclose the cutter blades, except at contact points where stock is being cut, on the following types of machines:

- (1) Shoe last and spoke lathes.
- (2) Doweling machines.
- (3) Heel-turning machines.
- (4) Automatic turning lathes with rotating knives.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, 49.17.060. WSR 15-24-102, § 296-806-45016, filed 12/1/15, effective 1/5/16; WSR 04-14-028, § 296-806-45016, filed 6/29/04, effective 1/1/05.]