

WAC 296-806-47002 Follow these requirements for machine initiation. (1) You must make sure all of the following occur before starting machines:

- (a) Select "normal" operation mode.
- (b) Safeguards are in place and functioning.
- (c) No workers are within the hazard zones.
- (d) Other proper work practices are followed.

(2) You must make sure in the "jog mode," the machine function is initiated by the operator either:

- (a) During set-up; or
- (b) By threading the material through the forming rolls.

(3) Make sure only assigned test employees perform machine testing and start-up.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, 49.17.060. WSR 15-24-102, § 296-806-47002, filed 12/1/15, effective 1/5/16; WSR 04-14-028, § 296-806-47002, filed 6/29/04, effective 1/1/05.]