WAC 296-307-450 General requirements. Summary.

Employer responsibility:

Safeguard employees working with dip tanks.

The employer must meet the requirements	in this section:
CONSTRUCTION	
Construct safe dip tanks.	WAC 296-307-45005
VENTILATION	
Provide proper ventilation for the vapor area.	WAC 296-307-45010
The employer must take additional precautions if the ventilation system recirculates exhaust air into the workplace.	WAC 296-307-45015
The employer must take additional precautions when using an exhaust hood.	WAC 296-307-45020
INSPECTION	
Periodically inspect dip tanks and associated equipment and correct any deficiencies.	WAC 296-307-45025
FIRST AID	
Make sure employees working near dip tanks know appropriate first-aid procedures.	WAC 296-307-45030
CLEANING	
Prepare dip tanks before cleaning.	WAC 296-307-45035
WELDING	
Protect employees during welding, burning or other work using open flames.	WAC 296-307-45045
LIQUIDS HARMFUL TO SKIN	
Provide additional protection for employees working near dip tanks that use liquid that may burn, irritate, or otherwise harm the skin.	WAC 296-307-45050

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, and 49.17.060. WSR 20-21-091, § 296-307-450, filed 10/20/20, effective 11/20/20; WSR 03-10-068, § 296-307-450, filed 5/6/03, effective 8/1/03; WSR 97-09-013, recodified as § 296-307-450, filed 4/7/97, effective 4/7/97. Statutory Authority: RCW 49.17.040, [49.17.]050 and [49.17.]060. WSR 96-22-048, § 296-306A-450, filed 10/31/96, effective 12/1/96.]