

WAC 296-803-40010 Make sure lockout and tagout devices meet these requirements. You must make sure lockout and tagout devices meet all of the following:

- (1) Create **no** additional hazards.
- (2) Have a distinctive design or appearance.
- (3) Are the only devices used for controlling energy.
- (4) Are **not** used for any other purpose.
- (5) Are durable enough to withstand the environment they are used in for the maximum time they are expected to be used.
- (6) Are standardized within the facility by color, shape, or size.
- (7) Identify the person applying the device.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, and 49.17.060. WSR 17-18-075, § 296-803-40010, filed 9/5/17, effective 10/6/17; WSR 04-15-105, § 296-803-40010, filed 7/20/04, effective 11/1/04.]