

WAC 296-806-42066 Block the skip bucket and counterweight guides. You must make sure the skip bucket and counterweight are blocked in their guides when the brake or any part of the drive train between the brake and the drum shaft are being repaired or replaced.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, 49.17.060. WSR 15-24-102, § 296-806-42066, filed 12/1/15, effective 1/5/16; WSR 04-14-028, § 296-806-42066, filed 6/29/04, effective 1/1/05.]