

**WAC 296-806-42044 Provide grating over silo and bunker openings for shuttle conveyors.** You must provide grating with openings to match the size of the material being discharged into silos or bunkers. Make sure openings are:

(1) Small enough so that workers cannot fall through.

(2) Protected by other effective means if the material size requires openings large enough for a worker to fall through.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, 49.17.060. WSR 15-24-102, § 296-806-42044, filed 12/1/15, effective 1/5/16; WSR 04-14-028, § 296-806-42044, filed 6/29/04, effective 1/1/05.]