

WAC 468-95-3015 Flagger procedures. Add a new Standard to MUTCD Section 6E.07 to read:

Standard:

Flagger directions at signalized intersections shall not be in conflict with signal displays and the signal must be either shut down or placed in flash mode as appropriate for the intersection operation except during emergencies.

[Statutory Authority: RCW 47.36.030. WSR 11-23-101, § 468-95-3015, filed 11/18/11, effective 12/19/11.]