WAC 16-662-120 Inspections of the net contents of packaged goods under NIST Handbook 133. WSDA will inspect packages using either "used dry tare" or "unused dry tare" in accordance with the procedures in NIST Handbook 133 and as defined in Appendix F Glossary. WSDA does not use "wet tare" in inspecting packages.

[Statutory Authority: RCW 19.94.190, 19.94.195, 19.112.020, 19.112.140, and chapter 34.05 RCW. WSR 14-19-033, § 16-662-120, filed 9/9/14, effective 10/10/14. Statutory Authority: Chapters 19.94, 19.112, and 34.05 RCW. WSR 12-02-021, § 16-662-120, filed 12/28/11, effective 1/28/12. Statutory Authority: Chapters 19.94 and 34.05 RCW. WSR 05-10-088, § 16-662-120, filed 5/4/05, effective 6/4/05.]